

4. Troubleshooting

IV. YC Delay

PAL BG	4
PAL DK	4
PAL I	4
SECAM BG	5
SECAM DK	5
SECAM L	4
NTSC 358	17
NTSC 443	1
AV PAL	1
AV SECAM	2
AV NT358	17
AV NT443	1
AV PAL60	17

V. Adjust

Video Mute time	8
Dynamic Dimming	Off
Dynamic CE	On
LNA Plus	
Megazine LNA	Off
DTV WatchDog	On
Main WatchDog	Off
UART Select	Off
Debug Mode	Normal
BackEndMute	Off
Tuner Select	ALPS_Slim
Tuner TOP Semco	10
Tuner TOP Alps	13
PixelShift Test	Off
FBE Select	FBE3
Hp Detextct	High
D WatchDog Count	0
Visual Test	Off

VI. Bus Stop

VII. Defect Log

- 1) LogList1
- 2) LogList2
- 3) LogList3